



STANDARD PRACTICES - ENGINE - INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF
VARIOUS PARTS TO SUPPORT COMMON NOZZLE ASSEMBLY REPAIRS. - CATEGORY CODE 7 -
MOD.NAC-70-0273

1. Planning Information

A. EFFECTIVITY

- (1) AIRCRAFT: Airbus A320
- (2) NACELLE: V2500-A1

B. REASON

To introduce the repair parts required to accomplish Repair Scheme VRS2299 Common Nozzle Assembly Pen NIB Fairing, Tail Piece Replacement.

C. COMPLIANCE

Category Code 7

D. APPROVAL

The Part Number transactions shown under the MATERIAL INFORMATION paragraph have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model Listed.

E. REFERENCES

- (1) Internal Reference No.
92VN507

F. GENERAL INFORMATION

- (1) Part numbers changed due to availability of various parts to support common nozzle assembly repairs.
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of various parts to support common nozzle assembly repairs.
- (3) Other publications affected
 - (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" Section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this bulletin.

V2500-NAC-70-0273



International Aero Engines
INFORMATION BULLETIN

- (1) The following repair parts are required to accomplish Repair Scheme VRS2299

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
740-1007-9 (78-11-11)	1	RQ*	Tailpiece	(01-260)	(A)
NAS1739C5-2 (78-11-11)	1	RQ*	Rivet	- - - - (01-270) (01-280)	(A)

(A) The new parts are currently available.

NOTE: The estimated 1994 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spares Parts Sales Department for information concerning firm price.

Printed in Great Britain

V2500-NAC-70-0273