

**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

SB No. V2500-NAC-70-0408

Revision No. 1

Subject: Nacelle Service Bulletin No. V2500-NAC-70-0408

Revision No. 1, dated July 15, 1996

THIS IS A COMPLETE REISSUE - The subject Bulletin No. V2500-NAC-70-0408 constitutes the complete instruction. The contents are in accordance with the following list of effective pages.

PAGE NO.

REVISION NO.


DATE

1 through 3

1

July 15, 1996

NOTE: A copy of this notice should be filed as a permanent record with each copy of subject Service Bulletin revision and with any future revisions.



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF NEW
WASHER FOR VSCF CONTROL CABLE SUPPORT
BRACKET.

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

24-21-00

Compliance Category Code

7


Internal Reference No.

94VN986/01

MAY 2/95
Revision No. 1 - JULY 15/96

V2500-NAC-70-0408

Page 1 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

**INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF
NEW WASHER FOR VSCF CONTROL CABLE SUPPORT
BRACKET.**

R NOTE: This service bulletin has been superseded by Service Bulletin V2500-
R NAC-24-0011.

A. EFFECTIVITY

- (1) AIRCRAFT: MD90
- (2) NACELLE: V2500-D5

B. REASON

To announce the availability of new washer for improved clearance of VSCF control cable support bracket.

C. COMPLIANCE

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. APPROVAL

The part number transactions shown under the MATERIAL INFORMATION paragraph have been shown to comply with applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. REFERENCES

- (1) IAE Engineering Change No. 94VN986.

F. GENERAL INFORMATION

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of new washers for VSCF control cable support bracket.
- (2) Other publications affected.

MAY 2/95

Revision No. 1 - JULY 15/96

V2500-NAC-70-0408

Page 2 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

- (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (b) The V2500 Power Plant Buildup Manual will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500-D5 Nacelle to incorporate this Bulletin.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
NAS1587-4C (24-21-46)	2	1.00	Washer	S700W1352-4 (05-086)	(A)(B)(1)

- (A) The new part is currently available.
- (B) Old part can continue to be used for other applications.
- (1) Old part number may be used as a replacement only where old part number was installed. New part number is acceptable replacement for the old or new part number.

NOTE: The estimated 1995 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm prices.

MAY 2/95
Revision No. 1 - JULY 15/96

V2500-NAC-70-0408

Page 3 of 3