

International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

Date March 18, 1998

Subject: Transmittal of Revision 1 to Information Bulletin
V2500-NAC-70-0608

Service Bulletin Revision History:

<u>Event</u>	<u>Date</u>
Basic Issue	March 10/98
Revision 1	March 18/98

Reason for Issuance of Revision

(1) To add old part numbers that were replaced

Effect on Past Compliance

None

List of Effective Pages

<u>Page No.</u>	<u>Rev No.</u>	<u>Date</u>
1-4	1	Mar 18/98

V2500-NAC-70-0608

Transmittal
Page 1 of 1



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO INTRODUCE PART NUMBERS
NECESSARY TO REPAIR DAMAGED
BIFURCATION FAIRINGS ON THE
CNA. REPAIR SCHEME VRS 2641.

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

71-11-11

COMPLIANCE CATEGORY CODE

7


INTERNAL REFERENCE NO.

JG 98VN500

ISSUED MARCH, 10 1998
REVISION 1 MARCH 18, 1998

V2500-NAC-70-0608

Page 1 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO INTRODUCE PART NUMBERS
NECESSARY TO REPAIR DAMAGED
BIFURCATION FAIRINGS ON THE
CNA. REPAIR SCHEME VRS 2641

A. EFFECTIVITY

(1) Aircraft:

(a) MD-90

(2) Nacelle:

(a) V2500-D5

B. REASON

To announce the availability of parts necessary to perform repair
scheme VRS 2641.

C. COMPLIANCE

Category Code 7

D. APPROVAL

The part number transaction shown under the "MATERIAL
INFORMATION" portion of this Bulletin has been shown to comply
with the applicable Federal Aviation Regulations and are FAA-
APPROVED for the Engine Model listed.

E. REFERENCES

(1) IAE Engineering Change No. 98VN500


F. GENERAL INFORMATION

(1) The Material Information portion of this bulletin provides
the information concerning the availability of the part
required to perform repair scheme VRS 2641.

ISSUED MARCH, 10 1998
REVISION 1 MARCH 18, 1998

V2500-NAC-70-0608

Page 2 of 4



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

G. MATERIAL INFORMATION


Applicability: For each V2500 Nacelle to incorporate this Bulletin.

<u>New</u> <u>Part No</u> <u>(ATA No)</u>	<u>Qty</u>	<u>Est'd</u> <u>Unit</u> <u>Price(\$)</u>	<u>Keyword</u>	<u>Old</u> <u>Part No</u> <u>(IPC No)</u>	<u>Supply</u> <u>Status</u>
290-1264-505 (78-11-11-06-370)	1		Fairing	290-1264-501 (06-365)	(A)
290-1264-506 (78-11-11-06-380)	1		Fairing	290-1264-502 (06-375)	(A)
290-1264-507 (78-11-11-06-390)	1		Fairing	290-1264-503 (06-385)	(A)
290-1264-508 (78-11-11-06-400)	1		Fairing	290-1264-504 (06-395)	(A)
290-1264-509 (78-11-11-06-410)	1		Fairing	290-1264-501 (06-405)	(A)
290-1264-510 (78-11-11-06-420)	1		Fairing	290-1264-502 (06-415)	(A)
290-1264-511 (78-11-11-06-430)	1		Fairing	290-1264-503 (06-425)	(A)
290-1264-512 (78-11-11-06-440)	1		Fairing	290-1264-504 (06-435)	(A)
CR3522-5-02 (78-11-11-06-130)	AR		Rivet		(A)
CR3552-5-03 (78-11-11-06-150)	AR		Rivet		(A)

ISSUED MARCH, 10 1998
REVISION 1 MARCH 18, 1998

V2500-NAC-70-0608

Page 3 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

2ASPFUEU06-15 (78-11-11-06-110)	AR	Pin	(A)
------------------------------------	----	-----	-----

ASPFSEU06 (78-11-11-06-180)	AR	Sleeve	(A)
--------------------------------	----	--------	-----

ASPLC2AC06 (78-11-11-06-190)	AR	Collar	(A)
---------------------------------	----	--------	-----

(A) New parts are currently available.

NOTE: The estimated 1998 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the BFGoodrich Price Catalog or contact BFGoodrich spare parts sales department for information concerning firm prices.

ISSUED MARCH, 10 1998
REVISION 1 MARCH 18, 1998

V2500-NAC-70-0608

Page 4 of 4