



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Mar.23/05

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES NACELLE SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin NV2500-70-0734 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 3 of the Service Bulletin	Reason for change Initial issue
--------	--	------------------------------------

Supplement Initial Issue

Remove	Incorporate Page 1	Reason for change Initial issue
--------	-----------------------	------------------------------------

V2500-NAC-70-0734

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		Mar.23/05
---	--	-----------

2		Mar.23/05
---	--	-----------

3		Mar.23/05
---	--	-----------

Supplement		
------------	--	--

1		Mar.23/05
---	--	-----------

Printed in Great Britain

INFORMATION – NACELLE – TO ANNOUNCE THE AVAILABILITY OF NEW RACEWAYS FAN HARNESS
SUPPORT BRACKETS

1. Planning Information

A. Effectivity

- (1) Airbus A319
V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
V2500-A1 Engines.
V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
V2530-A5, V2533-A5 Engines.

B. Reason

To announce the availability of new Raceways Fan Harness Support Brackets in new locations.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change No.01VN756.
- (2) ATA Locator – 71-51-50.

F. General Information

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of the new Raceways Fan Harness Support Brackets.



(2) Other publications affected:

- (a) The following Engine Illustrated Parts Catalogs will be revised to include the new Parts. See Material Information section for ATA Locations:

A320/V2500-A1 (S-V2500-1IA)

A321/V2530-A5 (S-V2500-2IA)

A321/V2533-A5 (S-V2500-5IA)

A319/V2522/V2524/V2527M-A5 (S-V2500-6IA)

A320/V2527/V2527E-A5 (S-V2500-7IA)

- (b) The A320/V2500-A1, A319/A320/A321/V2500-A5 (CMM-MECH V2500-1IA) Component Maintenance Manual will be revised to include the new Parts. See Material Information section for ATA Locations.

2. Material Information

A. Parts affected by this Service Bulletin:

V2500-A1 and A5 Engines

71-51-50

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
98001	740-5132-501	1	.Bracket, Support	740-5132-502	(A)(S1)
99001	740-5132-503	1	.Bracket, Support	740-5132-504	(A)(S1)

B. Instructions Disposition Codes:

(A) New part is currently available.

(S1) New part coded (S1) is fully and freely interchangeable with old part coded (S1).

3. Accomplishment Instructions

None.

INFORMATION – NACELLE – TO ANNOUNCE THE AVAILABILITY OF NEW RACEWAYS FAN HARNESS
SUPPORT BRACKETS

SUPPLEMENT – PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. New Production Parts:

Part No.	Desc.	Unit Price US Dollars
740-5132-501	Bracket	689.00
740-5132-503	Bracket	689.00