

International Aero Engines

RR-DERBY

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE: 860 565 5515 FAX: 860 565 0600 P.O. BOX 31, DERBY TELEGRAMS – 'ROYCAR' DERBY TELEX – 37645 TELEPHONE – DERBY 242424

DATER Apr. 3/03

V2500-A1/A5 SERIES NACELLE SERVICE BULLETIN

This document transmits Revision 1 to Service Bulletin NV2500-70-0736

Document History

Service Bulletin Revision Status Initial Issue Jan.28/03 Supplement Revision Status

Bulletin Revision 1

Remove Incorporate Reason for change
All pages of the Pages 1 to 3 of the Service Bulletin Service Bulletin 7 which was inadvertently omitted from Initial issue

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 are as follows:

<u>Page</u>		<u>Revision Number</u>	Revision Date
Bu	lletin		
R	1	1	Apr.3/03
R	2	1	Apr.3/03
R	3	1	Apr.3/03

INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF A NEW IDG HARNESS WITH A NEW IMPROVED PYLON CONNECTOR

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Nacelles.
- (2) Airbus A320
 - (a) V2500-A1 Nacelles.
 - (b) V2527-A5, V2527E-A5 Nacelles.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Nacelles.

B. Reason

To announce the availability of a new IDG Harness with a new improved Pylon Connector.

C. Compliance

R Category 7.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change No. 02VN769.
- (2) Airbus aircraft modification No. 32943.
- (3) ATA Locator 24-21-43.

F. General Information

(1) The new IDG Harness has been fitted with a new improved Pylon Connector.

Jan 28/03 R Apr. 3/03



- (2) The new Pylon Connector is procured from a new supplier. Experience has shown that on other Aircraft models where similar connectors from the new supplier have been fitted that reliability has improved.
- (3) Publications affected.
 - (a) V2500-A1 Engine Illustrated Parts Catalog will be revised to include the new IDG Harnesses. See Material Information section for ATA locations.
 - (b) All V2500-A5 Engine Illustrated Parts Catalogs will be revised to include the new IDG Harnesses. See Material Information section for ATA locations.



2. <u>Material Information</u>

A. Parts affected by this Service Bulletin:

24-21-43

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01-010	740-5869 -507	1	.IDG Harness	-	740-5869 -505	(A)

B. <u>Instructions Disposition Codes</u>

(A) New parts are available.

3. Accomplishment Instructions

None.

