400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600 P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

DATE: Jun. 8/05

V2500-A1/A5 SERIES NACELLE SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin NV2500-70-0779 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove Incorporate Reason for change

Pages 1 to 3 of the Initial issue

Service Bulletin

<u>Supplement Initial Issue</u>

Remove Incorporate Reason for change

Page 1 Initial issue

V2500-NAC-70-0779
Transmittal - Page 1 of 2

Printed in Great Britain

Printed in Great Britai

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	Revision Number	Revision Date
Bulletin		
1		Jun.8/05
2		Jun.8/05
3		Jun.8/05
Supplement		
1		Jun.8/05



<u>INFORMATION - NACELLE - THRUST REVERSER - ANNOUNCEMENT OF NEW HEAT SHIELD AT THE 7A BLEED PORT</u>

1. Planning Information

A. Effectivity

(1) Airbus A319

V2522-A5, V2524-A5, V2527M-A5 Nacelles.

(2) Airbus A320

V2500-A1 Nacelles.

V2527-A5, V2527E-A5 Nacelles.

(3) Airbus A321

V2530-A5, V2533-A5 Nacelles.

B. Reason

Under certain conditions, there is interference between the seal of the 7A bleed port silencer and the surrounding heat shield.

C. Compliance

Category 7

Accomplish when the supply of superseded parts has been depleted.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No. EASA.21J.031. The authorising IAE document is EC 02VN709. In addition, the part number changes and/or part modifications that are given in sections 2 and 3 of this Service Bulletin comply with the applicable Federal Aviation Authority Regulations and are FAA approved for the engine model(s) listed.

E. General Information

- (1) IAE Engineering Change No. 02VN709.
- (2) ATA Locator 78-30-00.

Jun. 8/05 Jun. 8/05 V2500-NAC-70-0779



- (3) Publications affected
 - (a) The V2500 Thrust Reverser Component Maintenance Manual (CMM-TR-V2500-1IA) will be revised to include the new parts. See Section 2. Material Information for ATA locations.

Printed in Great Britai



2. Material Information

A. Affected Parts

78-30-00

Applicability: For each V2500 Thrust Reverser

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
50-505	740-0220-365	1	Heat Shield	_	740-0220-111	(A)(1)

B. Instructions disposition codes:

- (A) New parts are currently available.
- (1) Old and new part are freely and fully interchangeable.

3. Accomplishment Instructions

None.

Jun. 8/05 Jun. 8/05



<u>INFORMATION - NACELLE - THRUST REVERSER - ANNOUNCEMENT OF NEW HEAT SHIELD AT THE 7A BLEED PORT</u>

SUPPLEMENT - PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to Goodrich Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. Parts Required:

Part No.	Description	Unit Price US Dollars
740-0220-365	Heat Shield	1,774.00

Jun. 8/05 Jun. 8/05 V2500-NAC-70-0779
Supplement Page 1 of 1