



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515  
FAX:- 860 565 0600

DATE: Jan. 9/07

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE:- 44 (0) 1332 242424  
FAX:- 44 (0) 1332 249936

## V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin NV2500-70-0867

### Bulletin Initial Issue

Remove	Incorporate Pages 1 to 4 of the Service Bulletin	Reason for change Initial Issue
--------	--	------------------------------------

**V2500-NAC-70-0867**  
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		Jan.9/07
2		Jan.9/07
3		Jan.9/07
4		Jan.9/07

Printed in Great Britain

V2500-NAC-70-0867  
Transmittal - Page 2

INFORMATION – NACELLE – ANNOUNCEMENT OF AN ALTERNATE COUPLING1. Planning InformationA. Effectivity

- (1) Airbus A319
  - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
  - (a) V2500-A1 Engines.
  - (b) V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
  - (a) V2530-A5, V2533-A5 Engines.

B. Reason

To announce the availability of an alternate coupling.

C. Compliance

Category Code 7

Accomplish based upon experience with prior configuration.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031. The authorising IAE document is EC 03VN604. In addition, the part number changes and/or part modifications that are given in sections 2 and 3 of this Service Bulletin comply with the applicable Federal Aviation Authority Regulations and are FAA approved for the engine model(s) listed.

E. References

- (1) IAE Engineering Change No. 03VN604.
- (2) ATA Locator – 24-21-51.

**F. General Information****(1) Publications affected**

- (a) The A320/V2500-A1 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (b) All V2500-A5 Engine Illustrated Parts Catalogs will be revised to include the new parts. See "Material Information" section for ATA Locations.

## 2. Material Information

### A. Part Prices:

Not Applicable.

### B. Parts affected by this Service Bulletin:

Applicability: For each V2500-A1/A5 Electrical Power IDG .

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
24-21-51						
01-050	OMP4261-1	1	Coupling	-	OMP2505-9 (A)(S1)	

### C. Instruction/Disposition Codes:

(A) Alternate part.

(S1) Old and new parts are freely and fully interchangeable, both physically and functionally.

**3. Accomplishment Instructions.**

None.