400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

DATE: May. 3/05

P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES NACELLE SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin NV2500-70-0877 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove Incorporate Reason for change

Pages 1 to 3 of the Initial issue

Service Bulletin

<u>Supplement Initial Issue</u>

Remove Incorporate Reason for change

Page 1 Initial issue

V2500-NAC-70-0877

Printed in Great Britain

Printed in Great Britai

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	Revision Number	Revision Date
Bulletin		
1		May 3/05
2		May 3/05
3		May 3/05
Supplement		w 7/05
1		May 3/05



SERVICE BULLETIN

INFORMATION - NACELLE - ANNOUNCEMENT OF NEW BLANK CASCADES

1. Planning Information

A. Effectivity

(1) Airbus A319

V2522-A5, V2524-A5, V2527M-A5 Nacelles.

- (2) Airbus A320
 - (a) V2500-A1 Nacelles.
 - (b) V2527-A5, V2527E-A5 Nacelles.
- (3) Airbus A321

V2530-A5, V2533-A5 Nacelles.

B. Reason

Compliance with European directive 2003/11/ce, dated June 10th, 2004; notifies nacelle manufacturers of the restrictions of marketing and use of pentabromodiphenyl ether (pentabde) and octabromodiphenyl ether (octabde).

C. <u>Compliance</u>

Category Code 7

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

The authorising IAE document is EC 04VN707A. In addition, the part number changes and/or part modifications that are given in section 2 of this Service Bulletin comply with the applicable Federal Aviation Authority Regulations and are FAA approved for the engine models listed.

E. General Information

- (1) Part numbers changed due to the introduction of new compliant Blank Cascades.
- (2) IAE Engineering Change No. 04VN707A.
- (3) ATA Locators -78-32-00 CMM, 78-32-19 AIPC.

May. 3/05 May. 3/05

V2500-NAC-70-0877



(4) Publications affected:

- (a) The V2500 Thrust Reverser Assembly Component Maintenance Manual (CMM-TR-V2500-1IA).
- (b) Airbus Aircraft Illustrated Parts Catalog.

Printed in Great Britain



SERVICE BULLETIN

2. Material Information

A. Parts affected by this Service Bulletin:

Applicability: For each V2500-A1/A5 Thrust Reverser Assembly.

NEW PART NO. (ATA No.)	QTY	PART TITLE	OLD PART NO. (CMM No.)	INSTR DISP
745-0109-507 (78-30-00) (CMM)	1	.Blank Cascade	745-0109-501 (03-195) (04-195) (05-195) (06-195)	(A)(B)(S1)
(78-32-19) (AIPC)			(80-115) (81-115) (82-115) (83-115)	
745-0109-506 (78-30-00) (CMM) (78-32-19)	1	.Blank Cascade	745-0109-504 (05-335) (81-165)	(A)(B)(S1)
(AIPC) 745-0109-505 (78-30-00) (CMM) (78-32-19) (AIPC)	1	.Blank Cascade	745-0109-503 (04-335) (82-165)	(A)(B)(S1)

B. <u>Instruction/Disposition Codes:</u>

- (A) Old part will no longer be available.
- (B) New parts are currently available.
- (S1) Old and new part numbers are freely and fully interchangeable.

3. Accomplishment Instructions

None.

May. 3/05 May. 3/05



SERVICE BULLETIN

INFORMATION - NACELLE - ANNOUNCEMENT OF NEW BLANK CASCADES

SUPPLEMENT - PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable; parts supplied as single line items.

2. New Production Parts:

Part No.	Description	Unit Price US Dollars
745-0109-507 745-0109-506	Blank Cascade Blank Cascade	5363.00 5363.00
745-0109-505	Blank Cascade	5363.00

May. 3/05 May. 3/05