



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515  
FAX:- 860 565 0600

DATE: Oct.19/07

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE:- 44 (0) 1332 242424  
FAX:- 44 (0) 1332 249936

## V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin V2500-NAC-70-0880

### Service Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 4 of the Service Bulletin	Initial Issue.

# V2500-NAC-70-0880

Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain



INFORMATION – NACELLE – ANNOUNCEMENT OF NEW COMMON NOZZLE ASSEMBLY**1. Planning Information****A. Effectivity**

- (1) Airbus A320
  - (a) V2500-A1 Nacelles.
- (2) Airbus A319/A320/A321
  - (a) V2500-A5 Nacelles.

**B. Reason**

- (1) To announce the availability of an interchangeable Common Nozzle Assembly.

**C. Compliance**

- (1) Category Code 7.

Accomplish when supply of superseded parts has been depleted.

**D. Approval**

- (1) The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

In addition, the part number changes and/or part modifications that are given in section 2 and 3 of this Service Bulletin comply with the applicable Federal Aviation Authority Regulations and are FAA approved for the engine models listed.

**E. General Information**

- (1) This General Information Bulletin introduces a new improved Common Nozzle Assembly.
- (2) Publications affected
  - (a) The V2500-A1/A5 Common Nozzle Component Maintenance Manual (CMM-CN-V2500-1IA) will be revised to include the new parts. Refer to Section 2. "Material Information" for ATA locations.

**F. References**

- (1) Internal Reference No. :  
Engineering Change No. 01VN712C.
- (2) ATA Locator – 78-11-11.

## 2. Material Information

### A. Parts affected by this Service Bulletin:

Applicability: For all V2500-A1/A5 Common Nozzle Assemblies

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
78-11-11 (CMM)						
07-001	745-1007 -505	1	.Fairing Assy -	-	745-1007 -503	(A)(S1)
10-050	745-1101 -507	1	.Common Nozzle Assy -	-	745-1101 -505	(A)(B) (S1)(S4)
11-530	745-1102 -503	1	.Strut Assy -	-	745-1102 -501	(A)(S2)
01-060	-	1	.Nozzle Assy -	-	745-1101 -25	(D1)(S4)
07-120	740-1007 -41	1	.Skin Panel (LH) -	-	740-1007 -39	(A)(B) (S2)(S3)
07-130	740-1007 -42	1	.Skin Panel (RH) -	-	740-1007 -40	(A)(B) (S2)(S3)
07-140	740-1007 -43	1	.Tail Piece -	-	740-1007 -9	(A)(B) (S2)(S3)

### B. Instruction/Disposition Codes:

(A) Old part will no longer be available.

(B) New part is currently available.

(S1) Old and new part numbers are freely and fully interchangeable.

(S2) Old and new part numbers are not interchangeable.

(S3) New parts coded (S3) must replace the old parts coded (S3) as a complete set.

(S4) New parts coded (S4) must replace the old parts coded (S4) as a complete set.

(D1) Old part was removed not replaced.

**3. Accomplishment Instructions.**

None.