



STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE REVISED LENGTH EXCITER COOLING  
HOSES - CATEGORY CODE 7 - MOD.ENG-70-0089

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce the availability of Exciter Cooling Hoses which have revised length to prevent a foul between Hoses and Brackets.

C. Compliance

Category 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC89VJ090

F. General Information

(1) The two 5A0422 Air Inlet Hoses are provided as a replacement for the two 5A9183 Air Inlet Hoses.

(2) Other Publications Affected:

(a) V2500 Powerplant Illustrated Parts Catalog, Chapter/Section 75-27-49, Figure 01, will be revised to show the new part number.

(b) V2500 Engine Illustrated Parts Catalog, Chapter/Section 75-27-49, Figure 01, will be revised to show the new part number.

V2500-ENG-70-0089



International Aero Engines  
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
5A0422 (75-27-49)	1	285.00	.Hose, Air Inlet	5A9183 (01-100)	(A)(B)(1)
5A0422 (75-27-49)	1	285.00	.Hose, Air Inlet	5A9183 (01-500)	(A)(B)(1)

(A) New Part is currently available for sale.

(B) Old Part will no longer be available for sale.

(1) Old and New Part is freely and fully interchangeable, both physically and functionally.

NOTE: The estimated 1990 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0089