



STANDARD PRACTICES – ENGINE – INFORMATION – TO ANNOUNCE THE AVAILABILITY OF EXPENDABLE
PARTS TO PERMIT ACCESSORY COMPONENT REPLACEMENT ON AN INSTALLED ENGINE – NOT
APPLICABLE – MOD.ENG-70-0099

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce the availability of expendable parts which are used for replacement and maintenance of accessory components on an installed engine.

C. Compliance

Not applicable.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC89VJ109

ECM89VJ109-01

ECM89VJ109-02

EC89VJ109A

ECM89VJ109A-01


EC89VJ109B

ECM89VJ109B-01

EC89VJ109D

EC92VJ044

V2500-ENG-70-0099




F. General Information

- (1) A catalog sequence number of the expendable parts for use of accessory components replacement and maintenance is identified to show them in the Illustrated Parts Catalog.
- (2) Other Publications Affected:
 - (a) V2500 Powerplant Illustrated Parts Catalog, Chapter/Section 73-12-41, Fig 01, 73-13-42, Fig 01, 75-23-52, Fig 01, 75-31-42, Fig 01, 75-31-43, Fig 01, 79-23-51, Fig 01, 74-21-43, Fig 01 and Fig 02, 75-23-51, Fig 01, 79-21-43, Fig 01, 75-24-51, Fig 01 and 75-24-52, Fig 01, will be revised to show the expendable parts for accessory components.
 - (b) V2500 Engine Illustrated Parts Catalog, Chapter/Section 73-12-41, Fig 01, 73-13-42, Fig 01, 75-23-52, Fig 01, 75-31-42, Fig 01, 75-31-43, Fig 01, 79-23-51, Fig 01, 74-21-43, Fig 01 and Fig 02, 75-23-51, Fig 01, Fig 01, 79-21-43, Fig 01, 75-24-51, Fig 01 and 75-24-52, Fig 01, will be revised to show the expendable parts for accessory components.
 - (c) A320 Aircraft Maintenance Manual, 73-12-41, 73-13-42, 75-23-52, 75-31-42, 75-31-43, 79-23-51, 74-21-43, 75-23-51, 79-21-43, 75-24-52, Removal/Installation will be revised to include the expendable parts to be replaced, and 75-24-51 and 75-24-52 Approved Repair will be revised to include repair schemes.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5009493 (73-12-41)	1	1,342.00	..Tube, Tee Fitting	- (01-146)	(A)
5009528 (73-12-41)	1	268.00	..Nut	- (01-148)	(A)
MS9058-05 (73-12-41)	1	3.37	..Retainer	- (01-149)	(A)
M25988-1- 905 (73-12-41)	1	4.13	..Packing, Performed	- (01-150)	(A)
13260P2 (73-13-42)	1	45.50	..Union	- (01-150)	(A)
M25988-1- 905 (73-13-42)	1	4.13	..Packing, Performed	- (01-153)	(A)
13260P3 (73-13-42)	1	52.30	..Union	- (01-160)	(A)

V2500-ENG-70-0099



International Aero Engines

INFORMATION BULLETIN


Printed in Great Britain

M25988-1-907 (73-13-42)	1	4.13	..Packing, Performed	- (01-163)	(A)
13260P2 (73-13-42)	1	45.50	.. Union	- (01-170)	(A)
M25988-1-905 (73-13-42)	1	4.13	..Packing, Performed	- (01-173)	(A)
5A0838 (75-23-52)	1	112.00	..Union, Double-Ended	- (01-130)	(A)
5A0840 (75-23-52)	1	6.44	..Ring, Sealing Toroidal	- (01-133)	(A)
5A0839 (75-23-52)	1	167.00	..Union, Double-Ended	- (01-140)	(A)
5A0841 (75-23-52)	1	12.90	..Ring, Sealing Toroidal	- (01-143)	(A)
1666-4001 (75-31-42)	1	196.00	..Adaptor, Union	- (01-126)	(A)
STD831-1 (75-31-42)	1	12.20	..Ring, Sealing Toroidal	- (01-128)	(A)
1666-4003 (75-31-42)	1	168.00	..Adaptor, Union	- (01-131)	(A)
STD831-16 (75-31-42)	1	11.00	..Ring, Sealing Toroidal	- (01-133)	(A)
1666-4003 (75-31-42)	1	168.00	..Adaptor, Union	- (01-136)	(A)
STD831-16 (75-31-42)	1	11.00	..Ring, Sealing Toroidal	- (01-138)	(A)
1666-4003 (75-31-42)	1	168.00	..Adaptor, Union	- (01-141)	(A)
STD831-16 (75-31-42)	1	11.00	..Ring, Sealing Toroidal	- (01-143)	(A)
AS27467 (75-31-42)	1	22.50	..Union, No.4 Bearing Oil W	- (01-146)	(A)
STD831-11 (75-31-42)	1	9.70	..Ring, Sealing Toroidal	- (01-148)	(A)
1666-4003 (75-31-43)	1	168.00	..Adaptor, Union	- (01-126)	(A)
STD831-16 (75-31-43)	1	11.00	..Ring, Sealing Toroidal	- (01-128)	(A)
1666-4003 (75-31-43)	1	168.00	..Adaptor, Union	- (01-131)	(A)
STD831-16 (75-31-43)	1	11.00	..Ring, Sealing Toroidal	- (01-133)	(A)
AS27467 (75-31-43)	1	22.50	..Union, No.4 Bearing Oil W	- (01-136)	(A)
STD831-11 (75-31-43)	1	9.70	..Ring, Sealing Toroidal	- (01-138)	(A)
AS27468 (79-23-51)	1	21.50	..Union, Tube Double-Ended	- (01-140)	(A)
STD831-16	1	11.00	..Ring, Sealing Toroidal	-	(A)

V2500-ENG-70-0099

Apr. 15/93

Page 3




International Aero Engines
INFORMATION BULLETIN

(79-23-51)				(01-143)	
10-700305	2	22.90	..Grommet	-	(A)
(74-21-43)				(01-500)	
10-700305	2	22.90	..Grommet	-	(A)
(74-21-43)				(02-500)	
5863291-101	1	401.00	..Fitting	-	(A)
(75-23-51)				(01-150)	
5863292-101	1	192.00	..Seal, Boss	-	(A)
(75-23-51)				(01-155)	
MS21209F5-25	5	.92	..Insert, Screw Thread	-	(A)
(79-21-43)				(01-145)	
0F25-008	1	172.00	..Plug, Fuel	-	(A)
(79-21-43)				(01-151)	
0F25-020	1	32.00	..Packing, Performed	-	(A)
(79-21-43)				(01-153)	
BRES4985	1		..Rod end	-	(A)
(75-24-51)				(01-102)	
NAS509-5C	1		..Nut, Jam	-	(A)
(75-24-51)				(01-103)	
5874117-102	1		..Washer, Locking	-	(A)
(75-24-51)				(01-104)	
5873785-101	2		..Screw, Socket Head	-	(A)
(75-24-52)				(01-102)	
NAS620C6	2		..Washer	-	(A)
(75-24-52)				(01-103)	
BRES4-2580	1		..Rod end	-	(A)
(75-24-52)				(01-104)	
NAS509-4C	1		..Nut	-	(A)
(75-24-52)				(01-105)	
5874117-101	1		..Washer, Locking	-	(A)
(75-24-52)				(01-106)	
MS16995-16	4		..Screw, Socket Head	-	(A)
(75-24-52)				(01-107)	
NAS620C6	4		..Washer	-	(A)
(75-24-52)				(01-108)	
5873785-101	1	2,249.00	..Fitting, Return	-	(A)
(75-24-52)				(01-152)	
M25988-1-905	1	4.13	..Packing, Performed	-	(A)
(75-24-52)				(01-153)	
5873784-101	1	2,249.00	..Fitting, Press	-	(A)
(75-24-52)				(01-155)	
M25988-1-906	1	4.13	..Packing	-	(A)
(75-24-52)				(01-156)	
5863142-101	1	420.00	..Fitting, Drain	-	(A)
(75-24-52)				(01-158)	
M25988-1-904	1	4.13	..Packing	-	(A)
(75-24-52)				(01-159)	

Printed in Great Britain

V2500-ENG-70-0099



International Aero Engines

INFORMATION BULLETIN

5863143-103 1 763.00 ..Blanket, Insulation - (A)
(75-24-52) (01-161)

(A) New part is currently available.

NOTE: The estimated 1993 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0099

Apr.15/93

Page 5

