



STANDARD PRACTICES - ENGINE - INFORMATION - LP COMPRESSOR - TO ANNOUNCE A SECOND SOURCE
FOR TOWERSHAFT BEARINGS - CATEGORY CODE 8 - MOD.ENG-70-0120

Printed in Great Britain

1. Planning Information

A. Effectivity

- (1) Airplane: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To announce that a second source for the Towershaft Bearings has been introduced.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number changes and/or part modifications described in the Material Information portion of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.
EC88VJ624

F. General Information

- (1) The Material Information portion of this Bulletin provides the latest information concerning the availability of the Towershaft Bearings.
- (2) Other Publications Affected:
 - (a) The V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-05 and 72-32-16.

V2500-ENG-70-0120



International Aero Engines

INFORMATION BULLETIN


- (b) The V2500 Engine Manual, 72-32-05, Cleaning TASK 72-32-05-100-000, TASK 72-32-05-100-002, Inspection/Check TASK 72-32-05-200-000, TASK 72-32-05-200-002, and 72-32-16, Cleaning TASK 72-32-16-100-000, TASK 72-32-16-100-003, TASK 72-32-16-100-004, TASK 72-32-16-100-008, Inspection/Check TASK 72-32-16-200-000, TASK 72-32-16-200-003, TASK 72-32-16-200-004, TASK 72-32-16-200-008.

Printed in Great Britain

V2500-ENG-70-0120

May.31/91

Page 2



International Aero Engines INFORMATION BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None


B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
5A6223 or 5A0289 (72-32-05)	1	479.00	.Bearing, Roller Outer	5A6223	(A)(B)(1)
5A6231 or 5A0288 (72-32-16)	Ref	133.00	.Bearing, Roller Outer	— (01-250)	(2)
5A6228 or 5A0284 (72-32-16)	1	713.00	.Bearing, Roller Inner	5A6231 (01-240)	(A)(B)(1)
5A6229 or 5A0285 (72-32-16)	Ref	132.00	.Bearing, Roller Inner	— (01-300)	(2)
5A6230 or 5A0287 (72-32-16)	1	700.00	.Bearing, Roller Inner	5A6229	(A)(B)(1)
5A6221 or 5A0286 (72-32-16)	1	1,877.00	.Bearing, Roller Inner	5A6230	(A)(B)(1)
	Ref		.Bearing, Roller Inner	— (01-500)	(2)
			.Bearing, Roller	5A6221	(A)(B)(1)
			.Bearing, Roller	— (01-600)	(2)

H. Instruction/Disposition Code Statements:

- (A) New part is currently available for sale.
- (B) Old part will continue to be available for sale.
- (1) Old and new part is freely and fully interchangeable,
both physically and functionally.
- (2) New part is alternative to primary new part number.

V2500-ENG-70-0120



International Aero Engines

INFORMATION BULLETIN

NOTE: The estimated 1991 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0120

May.31/91

Page 4