



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - PROVIDE REPLACEMENT FAN CASE LINER
PANEL ASSEMBLIES - CATEGORY CODE 7 - MOD.ENG-70-0194

Printed in Great Britain

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To provide the replacement fan case liner panel assemblies for engines not incorporating IAE Service Bulletin V2500-ENG-72-0103.

C. Compliance

Category 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.

EC91VJ026

- (2) Other References

IAE Service Bulletin V2500-ENG-72-0103

F. General Information

- (1) The material information portion of this Bulletin provides the latest information concerning the availability of the replacement Fan Case Liner Panel Assemblies.
- (2) Other Publications Affected:
 - (a) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-87 will be revised to show any new part number.

V2500-ENG-70-0194



International Aero Engines
INFORMATION BULLETIN

(b) V2500 Engine Manual, 72-32-87, Cleaning, Inspection/Check will be revised to add the new part number.

G. Parts Affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Qty	Supply Status
5A1379 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0842 (02-100)	1	(A)(B)(1)
5A1379 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0842 (02-150)	1	(A)(B)(1)
5A1380 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0843 (02-200)	1	(A)(B)(1)
5A1381 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0844 (02-250)	1	(A)(B)(1)
5A1382 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0845 (02-300)	1	(A)(B)(1)
5A1379 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0842 (02-350)	1	(A)(B)(1)
5A1380 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0843 (02-400)	1	(A)(B)(1)
5A1380 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0843 (02-450)	1	(A)(B)(1)
5A1382 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0845 (02-500)	1	(A)(B)(1)
5A1382 (72-32-87)	1	1677.00	.Panel, A/O Fan Case Liner	5A0845 (02-550)		

(A) New parts will be available for sale when the old parts are exhausted.

(B) Old Part will no longer be available for sale when the old parts are exhausted.

(1) Old and New Part is freely and fully interchangeable, both physically and functionally.

NOTE: The estimated 1992 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0194