



STANDARD PRACTICES - ENGINE - INFORMATION - LP TURBINE - PROVIDE A NEW STAGE 4 LP -
TURBINE AIR SEAL ASSEMBLY - CATEGORY CODE 7 - MOD.ENG-70-0207

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To improve durability and provide interchangeability with other V2500 engine models

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

(1) Internal Reference No.

90VM016

F. General Information

The Material Information Section of this Bulletin provides the latest information concerning the availability of the stage 4 air seal assembly.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
3A1983 (72-50-33)	1	---	Seal, air Turbine Stg 4	3A0792 (01-150)	(A),(B),(S1)

V2500-ENG-70-0207

Oct.5/92

Page 1 of 2



International Aero Engines
INFORMATION BULLETIN

H. Instruction/Disposition Code Statement

- (A) New part is available for sale
- (B) Old part will continue to be supplied until existing supplies have been depleted.
- (S1) Old and new parts are freely and fully interchangeable

Printed in Great Britain

V2500-ENG-70-0207

Oct.5/92

Page 2