



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE A
REVISED QUANTITY OF NO.3 BEARING SHIMS - NOT APPLICABLE - MOD.ENG-70-0229

1. Planning Information

A. Effectivity

- (1) Aircraft : (a) Airbus A320
(b) Airbus A321
(c) McDonnell Douglas MD-90
- (2) Engine : (a) V2500-A1
(b) V2527-A5
(c) V2530-A5
(d) V2525-D5
(e) V2528-D5

B. Reason

To announce the correction of quantity information for shim as select-from-range item on the No.3 bearing internal gearbox and Support assembly.

C. Compliance

Category Code 7

Accomplish when the supply for superseded parts have been depleted.

D. Approval

The part number transaction shown under the Material Information portion of this bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.

EC92VJ058

F. General Information

- (1) The Material Information Section of this bulletin provides the latest information concerning the availability of the revised quantity of the No.3 bearing shims.
- (2) Other Publications Affected:

V2500-ENG-70-0229



International Aero Engines
INFORMATION BULLETIN

(a) The V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-10.

(3) The thickness of each shim as follows;

Part No. -----	Thickness of Shims -----
5A5379	0.008 in (0,2 mm)
5A5380	0.016 in (0,4 mm)
5A5381	0.032 in (0,8 mm)
5A5382	0.06 in (1,6 mm)

Printed in Great Britain

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5A5379 (72-32-10)	6		.SHIM	5A5379 (01-127)	(A) (C)
5A5380 (72-32-10)	Ref		.SHIM	5A5380 (01-128)	(A) (C)
5A5381 (72-32-10)	Ref		.SHIM	5A5381 (01-129)	(A) (C)
5A5382 (72-32-10)	Ref		.SHIM	5A5382 (01-130)	(A) (C)
5A5379 (72-32-10)	Ref		.SHIM	5A5379 (01-132)	(A) (C)
5A5380 (72-32-10)	Ref		.SHIM	5A5380 (01-133)	(A) (C)
5A5381 (72-32-10)	Ref		.SHIM	5A5381 (01-134)	(A) (C)
5A5382 (72-32-10)	6		.SHIM	5A5382 (01-135)	(A) (C)
5A5379 (72-32-10)	Ref		.SHIM	5A5379 (01-137)	(B) (C)

V2500-ENG-70-0229



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

5A5380 (72-32-10)	Ref	.SHIM	5A5380 (01-138)	(B) (C)
5A5381 (72-32-10)	Ref	.SHIM	5A5381 (01-139)	(B) (C)
5A5382 (72-32-10)	Ref	.SHIM	5A5382 (01-140)	(B) (C)
5A5379 (72-32-10)	Ref	.SHIM	5A5379 (01-142)	(A) (C)
5A5380 (72-32-10)	Ref	.SHIM	5A5380 (01-143)	(A) (C)
5A5381 (72-32-10)	Ref	.SHIM	5A5381 (01-144)	(A) (C)
5A5382 (72-32-10)	Ref	.SHIM	5A5382 (01-145)	(A) (C)

H. Instruction/Disposition Statements:

- (A) Quantity increased from 2 to 6.
- (B) Quantity is revised from AS-Required (A/R) to 6.
- (C) Select-Form-Range item.

NOTE: The estimated 1995 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0229

Jan.9/95

Page 3

