



STANDARD PRACTICES - ENGINE - INFORMATION - LP TURBINE - PROVIDE A NEW ACC MANIFOLD
MOUNTING BRACKET RIVET - CATEGORY CODE 7 - MOD.ENG-70-0243

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
Airbus A321
McDonnell Douglas MD90
- (2) Engine: V2500-A1
V2500-A5
V2500-D5

B. Reason

To announce the availability of new ACC manifold mounting bracket rivet.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The partnumber transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference


- (1) Internal Reference No.

92VM039

F. General Information

The Material Information Section of this Bulletin provides the latest information concerning the availability ACC clamp retaining rivets.

V2500-ENG-70-0243



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
AN123291 (75-24-49)	8	15.18	Rivet, Solid Univ.Head	AN123292 (02-210)	(A)(B)
AN123291 (75-24-49)	8	15.18	Rivet, Solid Univ.Head	AN123292 (03-210)	(A)(B)

H. Instruction/Disposition Code Statement

(A) New part is available for sale

(B) Old part no longer available for sale

NOTE: The estimated 1994 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0243