

International Aero Engines INFORMATION BULLETIN

Date: Mar.21/97

Subject: Transmittal of Revision 1 to Service Bulletin
No. V2500-ENG-70-0244

Service Bulletin Revision History:

Event	Date
Basic Issue	Mar.27/95
Revision 1	Mar.21/97

Reason for Issuance of Revision:

To amend the old and new part numbers for the Fan Frame Assembly of the basic configuration standard to coincide the IPC.

Effect on Past Compliance:


None.

List of Effective Pages:

Bulletin Page No.	Rev. No.	Effective Date
R 1	1	Mar.21/97
2	Basic	Mar.27/95
R 3	1	Mar.21/97

V2500-ENG-70-0244

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY
OF A NEW FAN FRAME ASSEMBLY

MODEL APPLICATION

V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR


72-32-00

Compliance Category Code

7

Internal Reference No.

EC92VJ038
EC92VJ038-01



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY
OF A NEW FAN FRAME ASSEMBLY

A. Effectivity

(1) Aircraft:

(a) McDonnell Douglas MD-90

(2) Engine:

(a) V2525-D5

(b) V2528-D5

B. Reason

To introduce a new fan frame assembly with an as cast fire protection wall at No.9 strut area. This wall had a hole and was plugged by plate welded on the hole.

C. Compliance

Category Code 7

Accomplish when the supply of the superseded parts have been depleted.


D. Approval

The part number transaction shown under the Material Information portion of this bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

Engineering Change Nos. EC92VJ038, ECM92VJ038-01.

Printed in Great Britain



International Aero Engines INFORMATION BULLETIN

F. General Information

- (1) The Material Information section of this bulletin provides the latest information concerning the availability of the new fan frame assembly.
- (2) The V2500 Engine Illustrated Parts Catalog, 72-32-03 will be revised to include the new part.

G. Material Information

	New		Est'd		Old		Supply
	Part No.	Qty	Unit	Price	Part No.	IPC No.	
	(ATA No.)			Keyword			Status
R	5A1438 (72-32-03)	1		.Fan Frame Assy	5A1466 (03-100)		(A) (B) (S1)

H. Supply Status Code Statement;

- (A) New part is currently available.
- (B) Old part is no longer be available.
- (S1) Old and New parts are freely and fully interchangeable both physically and Functionally.

NOTE: Part price is available on a quote basis only.
Contact IAE's Spare Parts Sales Department for information concerning firm prices.