



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF
NEW FAN EXIT GUIDE VANES WITH OUTER PLATFORMS OF REDUCED WEIGHT MATERIAL - CATEGORY
CODE 7 - MOD.ENG-70-0377

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A321
(b) McDonnell Douglas MD-90
- (2) Engine: (a) V2527-A5 Engines
(b) V2530-A5 Engines
(c) V2525-D5 Engines
(d) V2528-D5 Engines

B. Reason

To introduce new Fan Exit Guide Vanes with Fiber Reinforced Plastic (FRP) formed outer platforms.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the Material Information portion of this bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.

EC93VJ161

F. General Information

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of the new Fan Exit Guide Vanes.
- (2) V2500 Engine Illustrated Parts Catalog (S-V2500-2IA, S-V2500-3IA), Chapter/Section 72-32-00 and 72-32-88 will be revised to include new parts.
- (3) V2500 Engine Manual (E-V2500-1IA), Chapter/Section 72-32-00 Disassembly-04, Config-3 and Assembly-12, Config-3 will be revised.

V2500-ENG-70-0377



International Aero Engines
INFORMATION BULLETIN

(4) V2500 Engine Manual (E-V2500-3IA), Chapter/Section 72-32-00
Disassembly-04, and Assembly-12, will be revised.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
---	20	---	.Washer	5A0802 (01-337)	(C)(S1)
(72-32-00)					
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (06-100)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (06-300)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (06-500)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (06-700)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (07-100)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (07-300)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (07-500)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (07-700)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (08-100)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (08-300)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (08-500)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (08-700)	(A)(B)(S1)

Printed in Great Britain

V2500-ENG-70-0377



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (09-100)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (09-300)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (09-500)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (09-700)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (10-100)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (10-300)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (10-500)	(A)(B)(S1)
5A1513 (72-32-88)	1	3810.00	.VANE A/O FAN EXIT	5A1375 (10-700)	(A)(B)(S1)

H. Supply Status Code Statements:

- (A) New part is currently available.
- (B) Old part is no longer be available for sale.
- (C) Old part will continue to be supplied for old application.
- (S1) Old and new parts are interchangeable in sets by location.

NOTE: The estimated 1996 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0377

Sep.22/95

Page 3

