



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - DIFFUSER CASE ASSEMBLY - TO  
ANNOUNCE THE AVAILABILITY OF REPLACEMENT SEALING SLEEVES FOR THE REPAIR OF DIFFUSER  
CASE SEALING SLEEVES - NOT APPLICABLE - MOD.ENG-70-0437

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320, A321  
McDonnell Douglas MD-90

(2) Engine: V2500-A1 Engines  
V2527-A5 Engines  
V2530-A5 Engines  
V2525-D5 Engines  
V2528-D5 Engines

B. Reason

To announce the availability of newly released repair parts.

C. Compliance

For information only.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.  
  
90VA155A

F. General Information

New Repair Schemes being introduced into the V2500 Engine Manual (E-V2500-1IA) the V2500 Engine Manual (E-V2500-3IA) which require Special Spare Parts for their accomplishment.

ATA Ref. No.	Repair Schemes	Title
72-42-11	VRS 3041	Diffuser Case Assembly - Sleeve Replacement
72-42-11	VRS 3279	Diffuser Case Assembly - Sleeve Replacement

V2500-ENG-70-0437



International Aero Engines  
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
2A3117 (72-42-11)	1	284.00	..Sleeve, No. 4 Bearing Scavenge Tube	2A0459 (01-013)	(1) (A) (B)
2A3118 (72-42-11)	2	78.60	..Sleeve, Sealing Diffuser	2A1014 (01-014)	(1) (A) (B)

H. Instruction/Disposition Code Statements:

- (1) Old and new parts are freely and fully interchangeable, both physically and functionally.  
(A) New part is currently available.  
(B) Old part will continue to be supplied.

NOTE: The estimated 1995 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0437