



STANDARD PRACTICES – ENGINE – INFORMATION – TO ANNOUNCE THE INTRODUCTION OF ADDITIONAL
CLASSES OF PARTS FOR THE OIL SCAVENGE – PUMP GEARSHAFTS – CATEGORY CODE N/A –
MOD.ENG-70-0448

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A319.
(b) Airbus A320.
(c) Airbus A321.
(d) Boeing-Douglas Product Division MD-90.
- (2) Engines: (a) V2500-A1 Engines.
(b) V2522-A5 Engines.
(c) V2524-A5 Engines.
(d) V2527-A5 Engines.
(e) V2530-A5 Engines.
(f) V2533-A5 Engines.
(g) V2525-D5 Engines.
(h) V2528-D5 Engines.

B. Reason

To announce the introduction of additional classes of parts for the oil scavenge-pump gearshafts.

C. Compliance

For information only.

D. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. References


- (1) Internal Reference No.

EC95VF007 EC95VF007A
EC95VF007B

- (2) Other References

IAE Engineering Change Number 98VF007, 98VF007A and 98VF007B.

V2500-ENG-70-0448



International Aero Engines

INFORMATION BULLETIN

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of additional classes of parts for the oil scavenge-pump gearshafts.

G. Other Publications Affected

Illustrated Parts Catalogue (IPC), Chapter/Section 79-22-41.

Printed in Great Britain

V2500-ENG-70-0448

Nov. 13/98

Page 2



International Aero Engines
INFORMATION BULLETIN

2. Material Information

A. Kits necessary for this Information Bulletin:

None.


B. Parts affected by this Information Bulletin:

NEW PART No. (ATA No.)	QTY	EST'D	PART TITLE UNIT PRICE (\$)	OLD PART No. (IPC No.)	INSTR DISP
4P7010CL01 (79-22-41)	2		.Gear, Driven	- (01-071)	(A)
4P7010CL02 (79-22-41)	2		.Gear, Driven	- (01-072)	(A)
4P7010CL03 (79-22-41)	2		.Gear, Driven	- (01-073)	(A)
4P7010CL04 (79-22-41)	2		.Gear, Driven	- (01-074)	(A)
4P7010CL05 (79-22-41)	2		.Gear, Driven	- (01-075)	(A)
4P7094CL01 (79-22-41)	2		.Gear, Driven	- (01-231)	(A)
4P7094CL02 (79-22-41)	2		.Gear, Driven	- (01-232)	(A)
4P7094CL03 (79-22-41)	2		.Gear, Driven	- (01-233)	(A)
4P7094CL04 (79-22-41)	2		.Gear, Driven	- (01-234)	(A)
4P7094CL05 (79-22-41)	2		.Gear, Driven	- (01-235)	(A)
4B7009CL01 (79-22-41)	2		.Gear, Assembly of, Drive	- (01-181)	(A)
4B7009CL02 (79-22-41)	2		.Gear, Assembly of, Drive	- (01-182)	(A)

V2500-ENG-70-0448

Nov. 13/98

Page 3




International Aero Engines
INFORMATION BULLETIN

4B7009CL03 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-183)	(A)
4B7009CL04 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-184)	(A)
4B7009CL05 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-185)	(A)
4B7093CL01 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-241)	(A)
4B7093CL02 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-242)	(A)
4B7093CL03 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-243)	(A)
4B7093CL04 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-244)	(A)
4B7093CL05 (79-22-41)	2	.Gear, Assembly of, Drive	- (01-245)	(A)
4B7005CL01 (79-22-41)	1	.Gear, Assembly of, Drive	- (01-421)	(A)(S1)
4B7005CL02 (79-22-41)	1	.Gear, Assembly of, Drive	- (01-422)	(A)(S1)
4B7005CL03 (79-22-41)	1	.Gear, Assembly of, Drive	- (01-423)	(A)(S1)
4B7005CL04 (79-22-41)	1	.Gear, Assembly of, Drive	- (01-424)	(A)(S1)
4B7005CL05 (79-22-41)	1	.Gear, Assembly of, Drive	- (01-425)	(A)(S1)
4B7006CL01 (79-22-41)	2	.Gear, Assembly of, Driven	- (01-481)	(A)
4B7006CL02 (79-22-41)	2	.Gear, Assembly of, Driven	- (01-482)	(A)
4B7006CL03 (79-22-41)	2	.Gear, Assembly of, Driven	- (01-483)	(A)
4B7006CL04 (79-22-41)	2	.Gear, Assembly of, Driven	- (01-484)	(A)

Printed in Great Britain

V2500-ENG-70-0448



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

4B7006CL05 (79-22-41)	2	.Gear, Assembly of, Driven	- (01-485)	(A)
4P7020 (79-22-41)	1	.Ring, Retaining	- (01-188)	(A)(S2)
4P7020 (79-22-41)	1	.Ring, Retaining	- (01-248)	(A)(S3)
4P7020 (79-22-41)	1	.Ring, Retaining	- (01-488)	(A)(S4)

NOTE: The Unit Prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

C. Instruction Disposition Codes

- (1) (A) New parts are available.
- (2) (S1) Airbus A319/A320/A321 only.
- (3) (S2) Was ATA No. 79-22-41, 01-185.
- (4) (S3) Was ATA No. 79-22-41, 01-245.
- (5) (S4) Was ATA No. 79-22-41, 01-485.

V2500-ENG-70-0448

Nov.13/98

Page 5

