

### International Aero Engines

# **INFORMATION BULLETIN**

STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - HP SYSTEM MODULE - TO ANNOUNCE THE AVAILABILITY OF A NEW FIRST STAGE HPT OUTER AIRSEAL GASKET - CATEGORY CODE 7 - MOD.ENG-70-0478

#### 1. Planning Information

#### A. Effectivity

(1) Aircraft: Airbus A320

Airbus A321

McDonnell Douglas MD-90

(2) Engine: V2527-A5 Engines

V2530-A5 Engines V2525-D5 Engines V2528-D5 Engines

#### B. Reason

To provide a new option that contains a Stage 1 Turbine Outer Airsealing gasket with one that has increased thickness and a reversed profile.

#### C. <u>Compliance</u>

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

#### D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

#### E. <u>References</u>

(1) Internal Reference No.

92VA098

#### (2) Other References

V2500-A1 Engine Illustrated Parts Catalog (S-V2500-1IA) to add the new part.

V2500-A5 Engine Illustrated Parts Catalog (S-V2500-2IA) to add the new part.

V2500-D5 Engine Illustrated Parts Catalog (S-V2500-3IA) to add the new part.

V2500-ENG-70-0478

## International Aero Engines

INFORMATION BULLETIN

# F. General Information

(1) The Material Information portion of this Bulletin provides the latest information concerning the availability of Stage 1 Turbine Outer Air Sealing Gaskets.

#### G. Material Information

New		Est'd		Old	
Part No.		Unit		Part No.	Instructions
(ATA No.)	Qty	Price (\$)	Keyword	(IPC No.)	Disposition

Applicability: For all V2500-A1 Engines to incorporate this Service Bulletin:

2A3155	1	1000.00	Gasket Option	2A2371	(1) (A) (B)
(72-45-20)				(01-005)	
2A3156	1		.Gasket	2A2108	(1) (C)
(72-45-23)				(01-010)	

# H. <u>Instruction/Disposition Code Statements:</u>

- (1) Old and new parts are freely and fully interchangeable, both physically and functionally.
- (A) New part is currently available.
- (B) Old part will no longer be available for sale.
- (C) The 2A3156 Gasket is a detail ot he 2A3155 Gasket Option.

NOTE: The estimated 1996 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.