



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
AVAILABILITY OF AN ALTERNATIVE FRONT MOUNT TUBE ASSEMBLY - CATEGORY CODE 8 -
MOD.ENG-70-0490

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A320
(b) Airbus A321
- (2) Engine: (a) V2500-A1 Engines
(b) V2522-A5 Engines
(c) V2524-A5 Engines
(d) V2527-A5 Engines
(e) V2527E-A5 Engines
(f) V2530-A5 Engines

B. Reason

To provide the new material front mount tube assembly as an alternative.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.

EC94VJ021

F. General Information

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of an alternative front mount tube assembly.
- (2) V2500 Engine Illustrated Parts Catalog (S-V2500-1IA, S-V2500-2IA), Chapter/Section 71-21-11 will be revised to include new parts as an alternative.

V2500-ENG-70-0490



International Aero Engines
INFORMATION BULLETIN

G. Material Information

| New Part No. (ATA No.) | Qty | Est'd Unit Price (\$) | Keyword | Old Part No. (IPC No.) | Supply Status |
|------------------------------|-----|-----------------------------|------------------------------|------------------------------|------------------|
| 5A1698 (71-21-11) | 1 | | .Mount,A/O Tube ENG Front | 5A6025 (01-150) | (A)(B)(S1) |
| 5A6025 (71-21-11) | Ref | | .Mount,A/O Tube ENG Front | --- (01-150) | (A)(B)(S1) |

H. Supply Status Code Statements:

- (A) New part is currently available.
- (B) Old part will continue to be supplied.
- (S1) New part is introduced as alternative to new part coded (S2).

NOTE: The estimated 1997 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0490