

STANDARD PRACTICES - ENGINE - INFORMATION - ANNOUNCEMENT OF ALTERNATIVE FLEXIBLE TUBE
ASSEMBLIES - FOR INFORMATION ONLY - MOD.ENG-70-0567

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A319
(b) Airbus A320
(c) Airbus A321
(d) McDonnell Douglas MD-90
- (2) Engines: (a) V2500-A1 Engines prior to Serial No.V0362
(b) V2522-A5 Engines prior to Serial No.V10325
(c) V2524-A5 Engines prior to Serial No.V10325
(d) V2527-A5 Engines prior to Serial No.V10325
(e) V2527E-A5 Engines prior to Serial No.V10325
(f) V2530-A5 Engines prior to Serial No.V10325
(g) V2533-A5 Engines prior to Serial No.V10325
(h) V2525-D5 Engines prior to Serial No.V20200
(i) V2528-D5 Engines prior to Serial No.V20200

B. Reason

To announce alternative flexible tube assemblies.

C. Compliance

For Information Only.

D. Approval

The part numbers are given in the "Material Information" section of this Service Bulletin. They obey the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. References


- (1) Internal Reference No.

EC97VR012

F. General Information

The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.

V2500-ENG-70-0567



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition


Applicability: For each V2500 engine to have this bulletin.					
A1 Model					
M1545-1 (73-22-49)	1	296.00	Tube assy of, air, flexible - Disconnect to EEC (P2.5)	- (11-500)	(A)(B)
M1545-1 (73-22-49)	1		Tube assy of, air, flexible - Disconnect to EEC (P12.5)	- (12-500)	(A)(B)
A5 Model					
M1544-1 (73-22-49)	1	1861.00	Tube assy of, air, flexible - Disconnect to EEC (P4.9)	- (04-100)	(A)(C)
M1543-1 (73-22-49)	1	1840.00	Tube assy of, air, flexible - Disconnect to EEC (PB)	- (07-500)	(A)(E)
M1545-1 (73-22-49)	1		Tube assy of, air, flexible - Disconnect to EEC (P2.5)	- (11-500)	(A)(B)
M1545-1 (73-22-49)	1		Tube assy of, air, flexible - Disconnect to EEC (P12.5)	- (12-500)	(A)(B)
D5 Model					
M1542-1 (24-21-47)	1	3145.00	Tube assy of, oil - VSCF FCOC to VSFC generator	- (01-100)	(A)(F)
M1540-1 (24-21-47)	1	2888.00	Tube assy of, oil, - VSCF generator to VSCF FCOC	- (02-100)	(A)(G)

Printed in Great Britain

V2500-ENG-70-0567

Nov. 7/97

Page 2



M1541-1 (73-22-49)	1	2304.00	Tube assy of, air, flexible - Disconnect to EEC (P4.9)	- (03-500)	(A)(H)
M1538-1 (73-22-49)	1	2630.00	Tube assy of, air, flexible - Disconnect to EEC (PB)	- (07-100)	(A)(J)
M1539-1 (73-22-49)	1	2264.00	Tube assy of, air, flexible - Bulkhead to disconnect (P2)	- (08-100)	(A)(K)
M1541-1 (73-22-49)	1		Tube assy of, air, flexible - Disconnect to EEC (P2)	- (08-700)	(A)(H)
M1537-1 (73-22-49)	1	2725.00	Tube assy of, air, flexible - Disconnect to EEC (P2.5)	- (11-100)	(A)(L)
M1541-1 (73-22-49)	1		Tube assy of, air, flexible - Disconnect to EEC (P12.5)	- (12-500)	(A)(H)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Instruction Disposition Codes

- (A) New part is currently available.
- (B) Alternative to 107432, 556-1-15404-000, C39440
- (C) Alternative to 556-1-15365-100
- (E) Alternative to 556-1-15364-100
- (F) Alternative to 556-1-15818
- (G) Alternative to 556-1-15817
- (H) Alternative to 556-1-15774
- (J) Alternative to 556-1-15775
- (K) Alternative to 556-1-15821
- (L) Alternative to 556-1-15773

