



STANDARD PRACTICES - ENGINE - INFORMATION - INTRODUCTION OF ALTERNATIVE TITANIUM
BRACKETS - N/A - MOD.ENG-70-0568

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A319
(b) Airbus A320
(c) Airbus A321
- (2) Engines: (a) V2500-A1 Engines prior to Serial No.V0362
(b) V2522-A5 Engines prior to Serial No.V10252
(c) V2524-A5 Engines prior to Serial No.V10252
(d) V2527-A5 Engines prior to Serial No.V10252
(e) V2527E-A5 Engines prior to Serial No.V10252
(f) V2530-A5 Engines prior to Serial No.V10252
(g) V2533-A5 Engines prior to Serial No.V10252

B. Reason

To announce alternative titanium brackets.

C. Compliance

For information only.

D. Approval

The part numbers are given in the "Material Information" section of this Service Bulletin. They obey the applicable Federal Aviation Regulations and are FAA-APPROVED for engine model listed.

E. References


- (1) Internal Reference No.

EC97VR015

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.

V2500-ENG-70-0568



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status

A1 and A5 Models					
5W8383 (71-51-41)	Ref	Bracket		- (05-820)	(A)(B)
5W8315 (71-51-41)	Ref	Bracket		- (05-920)	(A)(C)
5W8382 (71-51-41)	Ref	Bracket		- (05-990)	(A)(E)
5W0089 (71-51-49)	Ref	Bracket		- (01-390)	(A)(F)
5W1999 (72-41-00)	Ref	Bracket Assy of		- (03-550)	(A)(G)
5W8357 (72-41-00)	Ref	Bracket		- (03-790)	(A)(H)
5W8361 (72-60-00)	Ref	Bracket		- (01-122)	(A)(K)
5W8358 (73-22-49)	Ref	Bracket		- (03-470)	(A)(L)
5W8246 (73-22-49)	Ref	Bracket		- (08-060)	(A)(M)
5W8261 (73-22-49)	Ref	Bracket		- (08-070)	(A)(N)
5W8314 (75-32-51)	Ref	Bracket		- (01-150)	(A)(P)
5W8327 (79-21-42)	Ref	Bracket		- (01-084)	(A)(R)
5W8377 (79-21-42)	Ref	Bracket		- (01-088)	(A)(T)
5W8537 (79-21-42)	Ref	Bracket		- (01-090)	(A)(U)

Printed in Great Britain

V2500-ENG-70-0568



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

5W8257 (79-21-42)	Ref	Bracket	- (01-350)	(A)(V)
5W8249 (79-21-49)	Ref	Bracket	- (04-070)	(A)(W)
5W8447 (79-21-49)	Ref	Bracket	- (06-070)	(A)(X)
A5 Models Only				
5W8366 (75-32-41)	Ref	Bracket, assy	- (01-070)	(A)(J)

NOTE: The 1997 unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Instructions Disposition Codes:

- (A) New part is currently available
- (B) Alternative to 6A4664
- (C) Alternative to 6A4667
- (E) Alternative to 6A4668
- (F) Alternative to 6A4669
- (G) Alternative to 6A4670
- (H) Alternative to 6A4671
- (J) Alternative to 6A4672
- (K) Alternative to 6A4673
- (L) Alternative to 6A4675
- (M) Alternative to 6A4676
- (N) Alternative to 6A4677
- (P) Alternative to 6A4680
- (R) Alternative to 6A4682
- (T) Alternative to 6A4683
- (U) Alternative to 6A4684
- (V) Alternative to 6A4685
- (W) Alternative to 6A4686
- (X) Alternative to 6A4687

V2500-ENG-70-0568

Oct.10/97

Page 3

