

INFORMATION BULLETIN

INFORMATION - DELETION OF REDUNDANT SUPPORT BRACKETS FROM THE COMBUSTION OUTER CASE

MODEL APPLICATION

V2525-D5 V2528-D5

BULLETIN INDEX LOCATOR

72-40-00


Compliance Category Code

Internal Reference No.

N/A

EC94VN409A

V2500-ENG-70-0584



INFORMATION BULLETIN

INFORMATION - DELETION OF REDUNDANT SUPPORT BRACKETS FROM THE COMBUSTION OUTER CASE

1. Planning Information

A. Effectivity

- (1) Aircraft
 - (a) Boeing-Douglas Product Division MD-90
- (2) Engines
 - (a) V2525-D5 Engines from V20175.
 - (b) V2528-D5 Engines from V20175.

B. Reason

To announce the deletion of four brackets, located on the flanges of the front and rear combustion outer casings (COC). Support brackets for the fire detection system are attached to these brackets.

The four brackets are replaced by standard brackets which are an integral fabricated assembly of the COC. The standard brackets were introduced by IAE V2500 Service Bulletin NAC-26-0008.

C. Compliance

For Information Only.

D. Approval

The part number transactions are given in the Material Information section of this Information Service Bulletin. They obey the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.


E References

- (1) IAE Engineering Change Number 94VN409A.
- (2) This Information Service Bulletin is only applicable to engines which have the IAE V2500 Service Bulletin that follows incorporated:

NAC-26-0008

NACELLE - FIRE PROTECTION - FIRE DETECTOR ASSEMBLIES AND SUPPORT BRACKETS, ACCESSORY AND CORE -REPLACEMENT OF


V2500-ENG-70-0584



INFORMATION BULLETIN

F. General Information

(1) The Material Information section of this Information Service Bulletin provides the latest information about the availability of the affected parts.



INFORMATION BULLETIN

2. Material Information

NEW PART No. (ATA No.)	QTY	EST'D UNIT PRICE (\$)	PART TITLE	OLD PART No. (IPC No.)	INSTR DISP
- (72-40-00)	1		Bracket, clipping	6A5512 (01-350)	(A)
- (72-40-00)	1		Bracket, clipping	6A5512 (01-360)	(A)
- (72-40-00)	1		Bracket, clipping	6A5515 (05-590)	(A)
- (72-40 - 00)	1		Bracket, clipping	6A5514 (05-600)	(A)

H. Instruction Disposition Codes

(A) Redundant Part.