



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Aug. 15/07

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0623

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 4 of the Service Bulletin	Reason for change Initial Issue.
--------	--	-------------------------------------

V2500-ENG-70-0623
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Aug.15/07
--	--	-----------

2		
---	--	--

		Aug.15/07
--	--	-----------

3		
---	--	--

		Aug.15/07
--	--	-----------

4		
---	--	--

		Aug.15/07
--	--	-----------

Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF A FAIRLEAD BRACKET PACKING
PIECE

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
 - (a) V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Engines.

B. Reason

- (1) To announce the availability of a Fairlead Bracket Packing piece.

C. Compliance

- (1) Category Code 7.
 - Accomplish when supply of superseded parts has been depleted.

D. Approval

- (1) The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

E. General Information

- (1) This General Information Bulletin introduces a packing piece. This part was incorrectly omitted from the CCTS baseline of spareable items.
- (2) Publications affected
 - (a) The V2500-A5 Engine Illustrated Parts Catalogs (S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB) will be revised to include the new part. Refer to Section 2. "Material Information" for ATA locations.

F. References

- (1) Internal Reference No. :
Engineering Change No. 97VN214.
- (2) ATA Locator - 29-11-49.

2. Material Information

A. Parts affected by this Service Bulletin:

Applicability: For all V2500-A5 Engines

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
29-11-49						
01-895	745-5143 -501	2	.Packing Piece	-	-	(A)

B. Instruction/Disposition Codes:

(A) New part is currently available.

3. Accomplishment Instructions.

None.