

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE: 860 565 5515
FAX: 860 565 0600

DATE: Jul. 1/03

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE - DERBY 242424

V2500-A1/A5 SERIES PROPULSION SYSTEM INFORMATION SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0740 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove	Incorporate Page 1 and 2 of the Service Bulletin	Reason for change Initial issue
--------	--	------------------------------------

Supplement Initial Issue

Remove	Incorporate Page 1	Reason for change Initial issue
--------	-----------------------	------------------------------------

V2500-ENG-70-0740
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Jul.1/03
--	--	----------

2		
---	--	--

		Jul.1/03
--	--	----------

Supplement		
------------	--	--

1		
---	--	--

		Jul.1/03
--	--	----------

Printed in Great Britain

V2500-ENG-70-0740
Transmittal - Page 2



INFORMATION – ANNOUNCEMENT OF A NEW 'PROFORM' CABIN AIR 'Y' INTERSECTION DUCT

Printed in Great Britain

1. Planning Information

A. Effectivity Data

- (1) Aircraft: Airbus A319/A320/A321
- (2) Nacelle: V2500-A1 and V2500-A5

B. Reason

To announce the availability of a new 'Proform' Cabin Air 'Y' Intersection Duct.

C. Compliance

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. Approval

The part number changes shown under the Material Information section of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

E. References

- (1) IAE Engineering Change No. 99VN761.
- (2) ATA Locator – 36-11-49.

F. General Information

- (1) Part numbers changed due to the introduction of a new Cabin Air 'Y' Intersection Duct from a new supplier ('Proform').
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of the new 'Proform' Cabin Air 'Y' Intersection Duct.
- (3) Other publications affected

The V2500 Engine Illustrated Parts Catalog, S-V2500-1IA, S-V2500-2IA, S-V2500-2IAB, S-V2500-3IA, S-V2500-3IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB Chapter/Section 36-11-49 will be revised to include the new parts. See 'Material Information' section for ATA locations.



2. Material Information

A. Parts affected by this bulletin:

36-11-49

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01300	740-5051 -507	1	.Duct	-	740-5051 -505	(A)(B) (1)

B. Instructions/Disposition Code Statements:

(A) New parts will become available when existing stock of old parts has been exhausted.

(B) Old parts will continue to be supplied until stock has been exhausted.

(1) Old and new parts are freely and fully interchangeable both physically and functionally.

3. Accomplishment Instructions

A. None.

INFORMATION – ANNOUNCEMENT OF A NEW 'PROFORM' CABIN AIR 'Y' INTERSECTION DUCTSUPPLEMENT – PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit

Not applicable. Parts supplied as single line items

2. New Production Parts

Part No.	Desc.	Unit Price US Dollars
740-5051-507	Duct	Price on request

