



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Mar.24/05

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0743 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 3 of the Service Bulletin	Reason for change Initial issue
--------	--	------------------------------------

Supplement Initial Issue

Remove	Incorporate Page 1	Reason for change Initial issue
--------	-----------------------	------------------------------------

V2500-ENG-70-0743

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
Bulletin		
1		Mar.24/05
2		Mar.24/05
3		Mar.24/05
Supplement		
1		Mar.24/05

Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF SPAREABLE BOLTS AT THE
HYDRAULIC DRAIN FILTER AND BRACKET ASSEMBLIES

1. Planning Information

A. Effectivity

- (1) Airbus A319
V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
V2500-A1 Engines.
V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
V2530-A5, V2533-A5 Engines.

B. Reason

To announce the availability of spareable Bolts at the Hydraulic Drain Filter and Bracket Assemblies.

C. Compliance

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change No.04VN753 issue 1.
- (2) ATA Locator – 29-11-43.

F. General Information

- (1) The Bolts at the Hydraulic Drain Filter and Bracket Assemblies are now spareable items.



(2) Publications affected:

- (a) V2500-A1/A5 Engine Illustrated Parts Catalogs will be revised to include the spareable Bolt. See Material Information section for ATA Locations.
- (b) V2500-A1/A5 Component Maintenance Manuals will be revised to include the spareable Bolt. See Material Information section for ATA Locations.

2. Material Information

A. Parts affected by this Service Bulletin:

Applicability: For V2500-A1 and all V2500-A5 Engines

29-11-43

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
01-903	AS21538	1	.Bolt	-	(A)

B. Instruction/Disposition Codes:

(A) New parts are available.

3. Accomplishment Instructions

None.

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF SPAREABLE BOLTS AT THE
HYDRAULIC DRAIN FILTER AND BRACKET ASSEMBLIES

SUPPLEMENT – PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. New Production Parts:

Part No.	Desc.	Unit Price US Dollars
AS21538	Bolt	29.00