



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - PROVIDE A SALEABLE FAIRING FOR THE REPAIR OF FUEL NOZZLE
AND SUPPORT ASSEMBLIES

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2527M-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

73-00-00

Compliance Category Code

8

Feb.22/00

Internal Reference No.

98VC045A

V2500-ENG-70-0781

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - PROVIDE A SALEABLE FAIRING FOR THE REPAIR OF FUEL NOZZLE
AND SUPPORT ASSEMBLIES

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A319, A320, A321
McDonnell Douglas MD-90
- (2) Engine: V2500-A1 Engines
V2522-A5 Engines
V2524-A5 Engines
V2527-A5 Engines
V2527E-A5 Engines
V2527M-A5 Engines
V2530-A5 Engines
V2533-A5 Engines
V2525-D5 Engines
V2528-D5 Engines

B. Reason

To provide spareable Fairings for the repair of the Fuel Nozzle Support Assemblies.

The 'compliance' statement and the procedures described in paragraph F of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-Approved for the Engine Model listed.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The Part Number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change 98VC045A.
- (2) V2500-A1 Engine Illustrated Parts Catalog (S-V2500-1IA) to add the new part.
- (3) V2500-A5 Engine Illustrated Parts Catalog (S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB), Chapter/Section 72-45-20, 72-45-25, 72-45-30) to add the new part.
- (4) V2500-D5 Engine Illustrated Parts Catalog (S-V2500-3IA, S-V2500-3IB) to add the new part.

Feb.22/00

V2500-ENG-70-0781

Page 2

Printed in Great Britain



F. General Information

(1) The Material Information portion of this Bulletin provides the latest information concerning the availability of saleable Fairings for the repair of the Fuel Nozzle Support Assemblies.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price(\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
------------------------------	-----	----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500-A1, V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5, V2525-D5, V2528-D5 Engine to incorporate this Service Bulletin.

2A3434 (73-13-41)	1		Fairing, Upper Right	2A1373-04 (01-010)	(1)(A)(B)
2A3435 (73-13-41)	1		Fairing, Upper Left	2A1373-05 (01-010)	(1)(A)(B)
2A3368 (73-13-41)	1		Fairing, Lower Right	2A1373-06 (01-010)	(1)(A)(B)
			OR		
2A3368 (73-13-41)	1		Fairing, Lower Right	2A0993-06 (01-010)	(1)(A)(B)
2A3369 (73-13-41)	1		Fairing, Lower Left	2A1373-07 (01-010)	(1)(A)(B)
			OR		
2A3369 (73-13-41)	1		Fairing, Lower Left	2A0993-07 (01-010)	(1)(A)(B)

H. Instructions/Disposition Code Statements:

- (1) New Parts are for repair only of the Fuel Nozzle Support Assemblies.
- (A) The new part is currently available.
- (B) The old part is not procureable.

NOTE: The estimated unit prices, if shown, are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

