



International Aero Engines

SERVICE BULLETIN

ENGINE - CANCELLED - CATEGORY CODE 4 - MOD.ENG-72-0064

SUBJECT: Cancellation of Engine Service Bulletin Number
V2500-ENG-72-0064 (Engine - H.P. Compressor - Introduction of
Support Bracket for Front Mounting During Transportation).

NOTICE: The content of Service Bulletin No. V2500-ENG-72-0064
is hereby cancelled. For record purposes, a copy of this notice,
attached to a copy of Service Bulletin No. V2500-ENG-72-0064
should be retained on file.

REASON: The Parts/Modification introduced by Service Bulletin No.
V2500-ENG-72-0064, have never been installed on a service
engine.

Printed in Great Britain

V2500-ENG-72-0064

Apr.13/90

Page 1 of 1

