

SERVICE BULLETIN

ENGINE — GASKET OPTION — ADDITION AND REMOVAL OF A NEW GASKET OPTION

<u>MODEL APPLICATION</u> V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5

BULLETIN ISSUE SEQUENCE

V2500 Series 72-0699

72-45-24

IAE PROPRIETARY INFORMATION

This document is the property of International Aero Engines (IAE). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain FAA or other government approval to do so, without IAE's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without IAE's express written permission is not authorized and may result in criminal and/or civil liability.

WARNING – This document contains technical data the export of which is or may be restricted by the Export Administration Act and the Export Administration Regulations (EAR), 15 C.F.R. parts 730-774. Diversion contrary to U.S. law is prohibited. The export, re-export, transfer or re-transfer of this technical data to any other company, entity, person, or destination, or for any use or purpose other than that for which the technical data was originally provided by IAE, is prohibited without prior written approval from IAE and authorization under applicable export control laws.

Export Classification: Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Compliance Category

9

P&W Distribution Code

V2500

October 24/19



Summary

The purpose of this Service Bulletin is to introduce and cancel Gasket Option, PN 2A4605. This gasket option was introduced to address a number of parts which were inadvertently installed in a small number of engines. This configuration is not optimal and therefore the gasket option has been cancelled.

Planning Information

Effectivity Data

Engine Models Applicable

V2522-A5, V2524-A5, V2527M-A5, V2527-A5, V2527E-A5, V2530-A5, V2533-A5 Engine Serial Nos. V18725 and V18783.

Concurrent Requirements

There are no concurrent requirements.

Reason

- 1. Condition: This Service Bulletin introduces and removes Gasket Option, PN 2A4605.
- 2. Background: Gasket Option, PN 2A4605 added detail Gasket, PN 2A2111 to location in between the High Pressure Turbine (HPT) case and the 2nd vane outer forward platform.
- 3. Objective: To introduce and cancel Gasket Option, PN 2A4605, to address a potential misconfiguration.
- 4. Substantiation: Gasket, PN 2A2111, a detail of Gasket Option, PN 2A4605, increase leakage of location 72-45-24-02-020. The increased leakage was conservatively analyzed and all part life margins were maintained. There is no adverse impact to the compressor operating line, HPT life, engine time on wing, or engine performance.
- 5. Effects of Bulletin on:

Removal/Installation: Not Affected.

Disassembly/Assembly: Not Affected.

Cleaning: Not Affected.

Inspection/Check: Not Affected.

Repair: Not Affected.

Testing: Not Affected.

Supplemental Information

None.

Description

Not Applicable.

Compliance

Category 9

For Information Only.

October 24/19



Approval Data

The compliance statement and the procedures described in this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model listed.

The aircraft Type Certificate (TC) holder has been informed of this change.

Manpower

1.	In Service	
		Not Applicable
2.	At Overhaul	
		Not Applicable

Weight and Balance

Weight Change

None.

Moment Arm

No Effect.

3. Datum

Engine Front Mount Centerline (Power Plant Station (PPS) 100)

Electrical Load Data

This Service Bulletin has no effect on the aircraft electrical load.

Software Accomplishment Summary

Not Applicable.

References

NOTE:

In 2014 IAE converted the V2500 Technical Publications to a new system. As a result of the conversion, some manuals were consolidated. All manuals received new P&W part numbers. To facilitate the use of this Service Bulletin, a Technical Publications conversion table is provided in the Appendix.

- V2500 Standard Practices and Processes, P&W Ref. PN 2A4414, Chapter/Section 70-01-00.
- V2500-A5 Series Illustrated Parts Catalog, P&W Ref. PN 2A4428, Chapter/Section 72-45-24.

Other Publications Affected

NOTE:

In 2014 IAE converted the V2500 Technical Publications to a new system. As a result of the conversion, some manuals were consolidated. All manuals received new P&W part numbers. To facilitate the use of this Service Bulletin, a Technical Publications conversion table is provided in the Appendix.

1. V2500-A5 Series Illustrated Parts Catalog, P&W Ref. PN 2A4428, Chapter/Section 72-45-24.

October 24/19



Interchangeability of Parts

Not Applicable.

Information in the Appendix

Alternate Accomplishment Instructions (No)

Progression Charts (No)

Added Data (Yes)

Revision to Table of Limits (No)

Inspection Procedures (No)



Material Information

Material — Price and Availability

- 1. Part prices were not available at the time of Service Bulletin publication. Contact IAE Spares Management & Logistics for firm quotations.
- 2. There is no kit provided to do this Service Bulletin.
- 3. Part availability information is provided in material data Instructions Disposition.

Industry Support Program

Not Applicable.

The material data that follows is for each engine.

For V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5 Engines:

New PN	Qty	Estimate of Unit Price (\$)	Keyword	Old PN	Instructions — Disposition
2A4605	1	*	GASKET OPTION	2A2373 (72-45-24-02-020 F)	(2)(C)(Q) (O1)(O2)

Instructions/Disposition Code Statements:

Parts Modification Conditions

Estimated part prices are provided when they are available at time of publication. The Estimate of Unit Price is only for planning purposes and does not constitute a firm quotation. An asterisk (*) is shown where part pricing information was unavailable. In either case, contact IAE Spares for firm quotations.

(2) The new part is a replacement part only, and cannot be obtained by modification of the old part.

Spare Parts Availability

- (C) The old part will continue to be supplied.
- (Q) The new part is not available.
- (O1) Gasket Option, PN 2A4605, consists of a Gasket, PN 2A0176, PN 2A2277, or PN 2A2111.
- (O2) Gasket Option, PN 2A2373, consists of a Gasket, PN 2A0176, or PN 2A2277.

Vendor Services or Special Components/Materials

Not Applicable.

Tooling — Price and Availability

Special tools are not required to accomplish this Service Bulletin.

Reidentified Parts

Not Applicable.

Other Material Information Data

Not Applicable.

October 24/19



Accomplishment Instructions

Not Applicable.



Appendix Added Data

Internal Reference Information

Revision No.	Reference Document	Origination
Original	EC18VA017 EC18VA018 EA19VC140	JO/RCM

Number values shown in parentheses adjacent to U.S. values are International System of units (SI) equivalents.

NOTE:

In 2014 IAE converted the V2500 Technical Publications to a new system. As a result of the conversion, some manuals were consolidated. All manuals received new P&W part numbers. To facilitate the use of this Service Bulletin, the following Technical Publications cross reference table is provided.

Technical Publications Cross Reference Table

Publication	Engine Model(s)	IAE IETM Pub Ref	P&W Part Number
ENGINE MANUAL — A1, A5	All	E-V2500-1IA	2A4407
CMM-EHC — A1, A5	All	EHC-V2500-1IA	2A4409
CMM-FN — A1, A5	All	FN-V2500-1IA	2A4410
CMM-MMC — A1, A5	All	MECH-V2500-1IA	2A4411
CMM-THD — A1, A5	All	THD-V2500-1IA	2A4412
TLM — A1, A5	All	T-V2500-1IA	2A4408
ENGINE MANUAL — D5	All	E-V2500-3IA	2A4416
CMM-EHC — D5	All	EHC-V2500-31A	2A4418
CMM-FN — D5	All	FN-V2500-3IA	2A4419
CMM-MMC — D5	All	MECH-V2500-3IA	2A4420
CMM-THD — D5	All	THD-V2500-3IA	2A4423
TLM — D5	All	T-V2500-3IA	2A4417
SPPM (SPM) — A1, A5, D5	All	SPP-V2500-1IA	2A4414
EIPC — A1	V2500-A1102Q00	S-V2500-1IA	2A4427



Publication	Engine Model(s)	IAE IETM Pub Ref	P&W Part Number
	V2522/V2524/V2527M-AQ02	S-V2500-6IA	2A4428
	V2522/V2524/V2527M-AQ03	S-V2500-6IB	
	V2522/V2524/V2527M-SQ02	S-V2500-6SA	
	V2522/V2524/V2527M-SQ03	S-V2500-6SB	
	V2522/V2524/V2527M-SQ04	S-V2500-6NA	
	V2522/V2524/V2527M-SQ05	S-V2500-6NB	
	V2527/V2527E-AQ02	S-V2500-7IA	
	V2527/V2527E-AQ03	S-V2500-7IB	
	V2527/V2527E-SQ02	S-V2500-7SA	
	V2527/V2527E-SQ03	S-V2500-7SB	
	V2527/V2527E-SQ04	S-V2500-7NA	
EIPC — A5	V2527/V2527E-SQ05	S-V2500-7NB	
EIPC — A5	V2530-AQ02	S-V2500-2IA	
	V2530-AQ03	S-V2500-2IB	
	V2530-SQ02	S-V2500-2SA	
	V2530-SQ03	S-V2500-2SB	
	V2530-SQ04	S-V2500-2NA	
	V2530-SQ05	S-V2500-2NB	
	V2533-AQ02	S-V2500-5IA	
	V2533-AQ03	S-V2500-5IB	
	V2533-SQ02	S-V2500-5SA	
	V2533-SQ03	S-V2500-5SB	
	V2533-SQ04	S-V2500-5NA	
	V2533-SQ05	S-V2500-5NB	
	V2525/V2528-AQ02	S-V2500-3IA	
EIPC — D5	V2525/V2528-AQ03	S-V2500-3IB	2A4426
	V2525/V2528-AQ04	S-V2500-3IC	