



International Aero Engines SERVICE BULLETIN

Service Bulletin No. : V2500-ENG-75-0039

Subject : Cancellation of Engine Service Bulletin V2500-ENG-75-0039
(AIR – INTRODUCTION OF A SHROUD TO THE HP COMPRESSOR
STAGE 7 BLEED VALVE).

Notice: The content of Service Bulletin V2500-ENG-75-0039 is hereby cancelled.
For record purposes, a copy of this notice, attached to a copy of Service
Bulletin V2500-ENG-75-0039 should be retained on file.

Reason: The part number introduced by Service Bulletin SB75-0039 has been
superseded by an alternative component introduced in SB75-0040. This was
done prior to the manufacture of SB75-0039 standard components, which as
a result did not enter service.

Jan. 12/00

V2500-ENG-75-0039

Page 1 of 1

