



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - ANNOUNCEMENT OF A NEW LOOP CLAMP AT CLIPPING
POINT CP 0891.

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

77-32-00

Compliance Category Code

7

Internal Reference No.

90VN064

Dec 9/92

V2500-NAC-70-0164

Page 1 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

**INFORMATION - ANNOUNCEMENT OF A NEW LOOP CLAMP AT CLIPPING
POINT CP 0891.**

A. EFFECTIVITY

- (1) AIRCRAFT: Airbus A320
- (2) NACELLE: V2500-A1

B. REASON

To correct improper conversion of Loop Clamp (SM44LC39H107RG) to Loop Clamp (TA025074-10, Alternate AS61908) on EC 89VR027 at CP 0891, Should have been Loop Clamp (400WSS12).

C. COMPLIANCE

Category Code 7

D. APPROVAL

The part number changes shown in paragraph G of this service bulletin have been sanctioned under a product development control system that has been approved by the DGAC (Direction Generale de l'Aviation Civile - France).

E. REFERENCES

- (1) IAE Engineering Change No. 90VN064.

F. GENERAL INFORMATION

- (1) Part number changed due to Loop Clamp being changed to a larger type.
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of the larger Loop Clamp.
- (3) Other publications affected.
 - (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

Dec 9/92

V2500-NAC-70-0164

Page 2 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

- (b) The V2500 Power Plant Illustrated Parts Catalog will be revised to include new parts. See "Material Information" section for ATA Locations.
- (c) The V2500 Component Maintenance Manual will be included the new parts. See "Material information" section for ATA Locations

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this Bulletin.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
400WSS12 (77-32-43)	1	\$ 7.00	Clamp	TA025074-10 (05-104)	(A) (1)

(A) The new parts are currently available

- (1) Old part number may be used as a replacement only where old part number was installed. New part number is acceptable replacement for the old or new part number.

NOTE: The estimated 1992 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

Dec 9/92

V2500-NAC-70-0164

Page 3 of 3