

**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF AN
IMPROVED THERMAL ANTI-ICE DUCT ASSEMBLY.

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

30-00-00

Compliance Category Code

7


Internal Reference No.

94VN376/01

MAY 2/95
Revision No. 1 - OCT 20/95

V2500-NAC-70-0404

Page 1 of 3



V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF AN IMPROVED THERMAL ANTI-ICE DUCT ASSEMBLY.

A. EFFECTIVITY

- (1) AIRCRAFT: MD90
- (2) NACELLE: V2500-D5

B. REASON

To announce availability of new duct assemblies with improved flexible joint design.

C. COMPLIANCE

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. APPROVAL

The part number transactions shown under the MATERIAL INFORMATION paragraph have been shown to comply with applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. REFERENCES

- (1) IAE Engineering Change No. 94VN376.

F. GENERAL INFORMATION

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of new duct assemblies.
- (2) Other publications affected.
 - (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

MAY 2/95
Revision No. 1 - OCT 20/95

V2500-NAC-70-0404

Page 2 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

- (b) The V2500 Power Plant Buildup Manual will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500-D5 Nacelle to incorporate this Bulletin.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
88270-5 (30-21-49)	1	8,246.00	Duct Assembly	88270-3 (05-020)	(A)(B)(1)
88271-3 (30-21-49)	1	24,609.00	Duct Assembly	88271-2 (05-300)	(A)(B)(1)
88270-6 (30-21-49)	1	8,246.00	Duct Assembly	88270-4 (06-020)	(A)(B)(1)
88272-3 (30-21-49)	1	15,921.00	Duct Assembly	88272-2 (06-300)	(A)(B)(1)

(A) New part is currently available.

(B) Old part will no longer be available.

(1) Old and new parts are freely and fully interchangeable both physically and functionally.

NOTE: The estimated 1995 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm prices.

MAY 2/95
Revision No. 1 - OCT 20/95

V2500-NAC-70-0404

Page 3 of 3