

**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO ANNOUNCE THE DELETION OF SHIMS
FOR THE NACELLE SUPPORT SYSTEM INSTALLATION.

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

71-14-00

Compliance Category Code

7


Internal Reference No.

94VN959B

August 13, 1996

V2500-NAC-70-0405

Page 1 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

**INFORMATION - NACELLE - TO ANNOUNCE THE DELETION OF SHIMS
FOR THE NACELLE SUPPORT SYSTEM INSTALLATION.**

A. EFFECTIVITY

- (1) AIRCRAFT: MD90
- (2) NACELLE: V2500-D5

B. REASON

To announce the deletion of shims.

C. COMPLIANCE

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. APPROVAL

The part number transactions shown under the MATERIAL INFORMATION paragraph have been shown to comply with applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. REFERENCES

- (1) IAE Engineering Change No. 94VN959B.

F. GENERAL INFORMATION

- (1) Product improvement eliminates need for shims.
- (2) The Material Information portion of this bulletin provides the latest information concerning the deleted shim.
- (3) Other publications affected.
 - (a) The V2500 Engine Illustrated Parts Catalog will be revised to delete the shim. See "Material Information" section for ATA Locations.

August 13, 1996

V2500-NAC-70-0405

Page 2 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

G. MATERIAL INFORMATION

Applicability: For each V2500-D5 Nacelle to incorporate this Bulletin.

| New Part No. (ATA No.) | Qty | Est'd Unit Price (\$) | Keyword | Old Part No. (IPC No.) | Supply Status |
|---------------------------|-----|--------------------------|---------|---------------------------|------------------|
| - (71-14-03) | | | Shim | S700S0497-72 (10-032) | (A)(1) |
| - (71-14-03) | | | Shim | S700S0497-72 (10-055) | (A)(1) |

(A) Old part is not available as a spare for replenishment.

(1) Part deleted.

NOTE: The estimated 1996 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm prices.

August 13, 1996

V2500-NAC-70-0405

Page 3 of 3