



STANDARD PRACTICES – ENGINE – INFORMATION – NACELLE – TO ANNOUNCE THE AVAILABILITY OF
PARTS TO SUPPORT THE REPAIR OF THE TAI RING – CATEGORY CODE 7 – MOD.NAC-70-0423

1. Planning Information

A. EFFECTIVITY

(1) AIRCRAFT: Airbus A320

(2) NACELLE: V2500-A1

B. REASON

To announce the introduction of repair parts for repairing/replacing a section of the TAI ring.

C. COMPLIANCE

Category Code 7

D. APPROVAL

(1) The change in definition subject of the Service Bulletin has been covered by an aircraft modification approved by the DGAC (Direction Generale de L'Aviation Civile – France).

E. REFERENCES

(1) Internal Reference No.

91VN551

F. GENERAL INFORMATION

(1) Part numbers added to introduce repair parts for repairing/replacing a section of the TAI ring.

(2) The Material Information portion of this bulletin provides the latest information concerning the availability of repair parts for repairing/replacing a section of the TAI ring.

(a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

(b) The V2500 Structural Repair Manual will be revised to include the new parts. See ATA section 54-10-00.

V2500–NAC–70–0423



International Aero Engines
INFORMATION BULLETIN

(c) The V2500 Engine Manual will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this bulletin.

- (1) The following repair parts are required to accomplish Repair Scheme VRS2738.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
740-3070-501 (71-11-11)	1	RQ*	TAI Ring Section	- (01-025)	(A)
740-7606-501 (71-11-11)	4	RQ*	Half Patch	- (01-027)	(A)

RQ* = Quote only basis

(A) New Parts on order

NOTE: The estimated 1995 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

Printed in Great Britain

V2500-NAC-70-0423