



STANDARD PRACTICES - ENGINE - INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF
NEW LINK BEARINGS WITH IMPROVED DURABILITY - CATEGORY CODE 8 - MOD.NAC-70-0439

1. Planning Information

A. EFFECTIVITY

- (1) AIRCRAFT: (a) Airbus A320
(b) Airbus A321
- (2) NACELLE: (a) V2500-A1
(b) V2500-A5

B. REASON

To announce the availability of new link bearings for the TAI, Starter Air and Cabin Air System Ducting.

C. COMPLIANCE

Category Code 8

Accomplish based upon experience with the prior configuration.

D. APPROVAL

The change in definition subject of this Service Bulletin has been covered by an aircraft modification approved by the DGAC (Direction Generale de l'Aviation Civile -France).

E. REFERENCES

- (1) Internal Reference No.
93VN100

F. GENERAL INFORMATION

- (1) Part numbers changed to introduce new link bearings with improved durability.
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of the new link bearings.
- (3) Other publications affected

V2500-NAC-70-0439



International Aero Engines
INFORMATION BULLETIN

- (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (b) The V2500 Power Plant Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500-A1 Nacelle to incorporate this Bulletin.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
P3A1830		\$443.00	Bearing, Link	RFY04UJ	(A)(B)(C)
(30-21-49)	2		Female	(01-170)	
(30-21-49)	3			(02-170)	
(36-11-49)	2			(01-160)	
(36-11-49)	1			(01-220)	
(80-13-49)	1			(01-060)	
(80-13-49)	2			(01-088)	
(80-13-49)	2			(01-125)	
(80-13-49)	2			(01-180)	
P3A1820		\$402.00	Bearing, Link	RMY04UJ	(A)(B)(C)
(30-21-49)	1		Male	(02-180)	
(36-11-49)	1			(02-230)	
(80-13-49)	1			(01-070)	


Applicability: For each V2500-A5 Nacelle to incorporate this Bulletin.

P3A1830		\$443.00	Bearing, Link	RFY04UJ	(A)(B)(C)
(30-21-49)	2		Female	(01-170)	
(30-21-49)	3			(02-170)	
(30-21-49)	1			(02-180)	
(36-11-49)	2			(01-160)	
(36-11-49)	1			(01-220)	
(80-13-49)	1			(01-060)	
(80-13-49)	2			(01-088)	
(80-13-49)	2			(01-125)	
(80-13-49)	2			(01-180)	
P3A1820		\$402.00	Bearing, Link	RMY04UJ	(A)(B)(C)
(36-11-49)	1		Male	(01-230)	
(80-13-49)	1			(01-070)	

(A) New parts are currently available.

(B) The old part will no longer be available for sale when the old part is exhausted.

V2500-NAC-70-0439



International Aero Engines

INFORMATION BULLETIN

(C) Not available as spare for replenishment.

NOTE: The estimated 1996 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

Printed in Great Britain

V2500-NAC-70-0439

Feb. 15/96

Page 3

