International Aero Engines

RR-DERBY

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE: 860 565 5515 FAX: 860 565 0600 P.O. BOX 31, DERBY TELEGRAMS – 'ROYCAR' DERBY TELEX – 37645 TELEPHONE – DERBY 242424

DATE: Aug. 6/03

V2500-A5 SERIES NACELLE SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin NV2500-70-0794 and the Initial Issue of the Supplement

Bulletin Initial Issue

Remove Incorporate Reason for change

Page 1 and 2 of the Initial issue

Service Bulletin

<u>Supplement Initial Issue</u>

Remove Incorporate Reason for change

Page 1 Initial issue

V2500-NAC-70-0794

Printed in Great Britain

Printed in Great Britai

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

Page	Revision	Number	Revision	Date

Bulletin	
1	Aug.6/03
2	Aug.6/03
Supplement	. (107
1	Aug.6/03

INFORMATION - NACELLE - ANNOUNCEMENT OF NEW TORQUE RING FAIRING ASSEMBLY

1. Planning Information

A. Effectivity

(1) Airbus A319

V2522-A5, V2524-A5, V2527M-A5 Nacelles.

(2) Airbus A320

V2527-A5, V2527E-A5 Nacelles.

(3) Airbus A321

V2530-A5, V2533-A5 Nacelles.

B. Reason

Improved part fit and function with interfacing parts.

C. Compliance

Category Code 7

Accomplish based upon experience with prior configuration.

D. Approval

The part number transaction shown under the Material Information section of this Information Service Bulletin has been shown to comply with the applicable Federal Aviation Regulations and is FAA-APPROVED for the Engine Models listed.

E. References

- (1) IAE Engineering Change No. 01VN701C.
- (2) ATA Locator -78-30-00.

F. General Information

- (1) Part numbers changed due to the introduction of new Fairing Assembly.
- (2) Publications affected:

The V2500 Thrust Reverser Component Maintenance Manual (CMM-TR-V2500-1IA) will be revised to include the new parts. See Material Information section for ATA locations.

Aug. 6/03

Aug. 6/03

V2500-NAC-70-0794

2. Material Information

A. Parts affected by this Service Bulletin:

Applicability: For V2500-A5 Thrust Reverser Serial Numbers N5945 and subsequent to incorporate this Bulletin

78-30-00

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
47760	745-0404-505	1	Fairing Assy	745-0404-503	(1)
48760	745-0404-506	1	Fairing Assy	745-0404-504	(1)

B. <u>Instruction/Disposition Codes:</u>

(1) New part may be used in place of old part but not vice versa.

3. Accomplishment Instructions

None.

Aug. 6/03 Aug. 6/03



INFORMATION - NACELLE - ANNOUNCEMENT OF NEW TORQUE RING FAIRING ASSEMBLY

SUPPLEMENT - PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. New Production Parts:

Part No.	Desc.	Unit Price US Dollars
745-0404-505	Fairing Assy	Price on request
745-0404-506	Fairing Assy	Price on request

Aug. 6/03 Aug. 6/03 V2500-NAC-70-0794
Supplement Page 1 of 1

